

TO BE FILLED BY THE INSPECTING OFFICER  
(Assistant Engineer / Assistant Executive Engineer)

Name of School FLOREAT INTERNATIONAL SENIOR SECONDARY SCHOOL

1. Name of the Officer : RITESH K.M.

2. Location Valiyaparamba, Pulikkal

3. Period for which the certificate is issued 2024-25 Academic year

4. Types of building RCC permanent building

5. Nature of defect if any  
1) Cellar floor

a) Foundation and basement

2x5.80x5.90x2.55  
1x6.10x5.90x2.55

1x5.95x5.90x3.55

1x6.00x5.90x3.55

b) Superstructure

1x6.45x6.00x3.55

1x5.90x6.00x3.55

1x7.20x5.45x2.55

c) Doors and windows

2) Ground floor

1x6.20x5.90x3.50

d) Wood work wrought and put up

1x5.90x5.90x3.50

1x6.00x5.90x3.50

e) Roof

2x5.90x3.50

1x5.90x5.90x3.30

f) Flooring

1x6.10x5.90x3.50

2x6.00x5.90x3.50

g) Miscellaneous (Cracks if any)

1x6.45x6.00x3.50

1x5.90x6.00x3.50

1x7.15x5.45x3.50

6. Any major defects noticed which will render the building unsafe in any manner

No

Total 20 Nos.

7. Whether maintenance work have been done properly

Yes

8. Whether the structure is sound or not for conducting classes.

Yes, sound under normal wind and weather conditions.

Note: 1 The Stability of the structure should be examined also with reference to location altitude intensity of wind exposure to flood etc.

2 Any additional observation deemed necessary for the Certificate, may be furnished separately with the Certificate.

Certified that the School was inspected by me on 04/07/24 and found to be, fit / unfit to conduct classes for the period for the reasons stated above.



Signature

Designation

**Assistant Engineer**  
**LID & EW Section**  
**Pulikkal Grama Panchayat**  
**Malappuram Dt. - 673 637**